

GRABIT® SCREW EXTRACTOR

PACKAGED	HEX DRIVE	LENGTH	SCREW SIZE	DOMESTIC	
				EVCO #	PRICE
BULK	1/4	1	#6 - #10	GB2	
CARDED			#6 - #10	GB2C	
BULK			#12 - #14	GB3	
CARDED			#12 - #14	GB3C	
CARDED			#6 - #14	GB23KC	

OPERATING INSTRUCTIONS

Burnishing:

1. Insert Grabit directly into drill or quick change chuck - Burnishing end showing (cutting end)
2. Set drill for reverse (COUNTERCLOCKWISE)
3. Place Burnishing end of tool into damaged screw, slowly clean inside screw head until smooth. Note: Burnishing tool end is not to be used to drill hole.

Removing:

4. Remove Burnishing end from chuck, flip tool, replace into drill chuck--Remover end now showing (spiral end)
5. Maintain reverse setting (COUNTERCLOCKWISE)
6. Place Remover end of tool into smooth screw head.
7. Apply firm downward pressure, drill at slow speed. Apply lowest level of power to hand drill.
8. Remover end of Grabit® will thread into screw head and remove.

